

This Technical Service Bulletin is supplied as technical information for field servicing and when used in conjunction with the ADU-42CF Service Manual enable a technician in the field to perform described corrections.

INTRODUCTION: Some customers may have experienced reduced water flow during use on the ADU-42CF Portable Field Sink. A limited number of ADU-42CF Portable Field Sinks manufactured by Aseptico in the 4th quarter of 2012 on Work Order #37958 may have been mis-wired at the 3-pin J3 location.

In order to correct the reduced water flow caused by mis-wiring of the J3 3-pin connector, this rewiring Service Bulletin has been made available. If after inspection the wires are found to be reversed, follow the rewiring instructions provided.

MODEL: ADU-42CF Portable Field Sink

SERIAL NUMBER(S):	<u>SERIAL NUMBER</u>	<u>SALES ORDER</u>	<u>RMA HISTORY</u>
	HCL3202012-00-01	401440	Inspection Required
	HCL3202012-00-02	401440	Inspection Required
	HCL3202012-00-05	401440	Inspection Required
	HCL3202012-00-09	401440	Inspection Required
	HCL3202012-00-14	401440	Inspection Required
	HCL3202012-00-19	401440	Inspection Required
	HCL3202012-00-20	401440	Inspection Required
	HCL3202012-00-21	401440	Inspection Required
	HCL3202012-00-22	401440	Inspection Required
	HCL3202012-00-30	404275	Inspection Required
	HCL3202012-00-33	404275	Inspection Required
	HCL3202012-00-34	404275	Inspection Required
	HCL3202012-00-35	404275	Inspection Required
	HCL3202012-00-36	404275	Inspection Required
	HCL3202012-00-37	404275	Inspection Required
	HCL3202012-00-38	404275	Inspection Required
	HCL3202012-00-39	404275	Inspection Required
	HCL3202012-00-40	404275	Inspection Required
	HCL3202012-00-41	404275	Inspection Required
	HCL3202012-00-42	404275	Inspection Required
	HCL3202012-00-43	404275	Inspection Required
	HCL3202012-00-44	404275	Inspection Required
	HCL3202012-00-45	404275	Inspection Required
	HCL3202012-00-46	404275	Inspection Required
	HCL3202012-00-47	404275	Inspection Required
	HCL3202012-00-48	404275	Inspection Required
	HCL3202012-00-49	404275	Inspection Required
	HCL3202012-00-50	404275	Inspection Required

REPAIR PROCEDURE: Refer to the Instructions for Rewiring the ADU-42CF Pump Wiring Harness document 421060.